Hupertherm



HYPERTHERM POWERMAX 45XP

- Smart Sense[™] technology automatically adjusts the gas pressure according to cutting mode and torch lead length for optimal performance.
- Boost Conditioner™ circuit (on CSA models) improves performance on low-line voltage, motor generators, and fluctuating input power.
- FastConnect™ torches, CNC interface, and four work lead styles increase versatility for handheld and mechanized use.
- · Simplified control panel with LCD screen for easy operation.

Pierce Capacity:	12mm (220V)
Input Voltages:	220V/380V
Input Amps (220V/380V):	22A/ 38A
Isolator / Circuit Breaker Value:	50A / 25A
Duty Cycle at full output:	50%
Output current	10-45A
Gas:	Air or Nitrogen
Power Consumption:	8kW
Used On Table:	WS



45xp (220V 12mm)/ 65 (12mm)/ 85 (16mm)/ 105 (22mm)

powermax 45 xp