

HYPERTHERM POWERMAX 85

- Smart Sense[™] technology automatically adjusts the gas pressure according to cutting mode and torch lead length for optimal performance.
- Boost Conditioner™ circuit (on CSA models) improves performance on low-line voltage, motor generators, and fluctuating input power.
- FastConnect™ torches, CNC interface, and four work lead styles increase versatility for handheld and mechanized use.
- Simplified control panel with LCD screen for easy operation.

Pierce Capacity:	16mm
Input Voltages:	380V
Input Amps (220V/380V):	38A
Isolator / Circuit Breaker Value:	40A
Duty Cycle at full output:	60%
Output current	25 – 85A
Gas:	Air or Nitrogen
Power Consumption:	20kW
Used On Table:	FS



45xp (220V 12mm)/ 65 (12mm)/ 85 (16mm)/ 105 (22mm)

powermax (%)